

To Be Completed by TAG Leads											TAG Meeting Results				
Blue - Current MN Amendment Purple - Code Change Proposal Red - Revisit											Recommendations A - Accept Model Code AM - Amend Model Code R - Reject				
Item Number	2024 IEBC Chapter	2024 IEBC Code Section	2021 IEBC Code Section	2020 MN Code Section	Code Section Heading/Topic	MN Amendment?	Description of change(s) to code language	Safety/Health Value	Cost Impact	Staff Comment	Staff Recommendation	TAG Recommendation	TAG Group Consensus	Stakeholder Consensus	Comments
								N - None, L - Low, M-Med, H-High					Y or N	Y or N	
Chapter 5 Prescriptive Compliance Method															
5-1	5	501.3	501.3		Health Care Facilities (Prescriptive Compliance)		Added in 2021, Group I-2, ambulatory care facilities and outpatient clinics alterations and additions electrical or med gas systems shall comply with NFPA 99.	H	L		A				
5-2	5	502.1	502.1		General (Additions)		Revised in 2024 - limits some structural compliance requirements, specifies addition of occupiable roof shall comply with IBC (with exception).	M		Coordinate with Structural TAG and obtain input on cost.					
5-3	5	502.1.1			Risk Category Assignment (Additions)		New in 2024.	M		Coordinate with Structural TAG and obtain input on cost.					
5-4	5	502.1.2			Creation or Extension of Nonconformity (Additions)		New in 2024 (with exception).	H		Coordinate with Structural TAG and obtain input on cost.					
5-5	5		502.2		Disproportionate Earthquake Damage (Additions) - Deleted		Eliminated in 2024.				A				
5-6	5	502.2		502.3	Flood Hazard Areas (Additions)		Renumbered and revised in 2024.			Coordinate with MR 1335 Floodproofing Regs.	A				
5-7	5	502.3	502.4	MR 1311.502.4	Existing Structural Elements Carrying Gravity Loads (Additions)	Y	Renumbered in 2024.			Send to Structural TAG.					
5-8	5	502.4	502.5	MR 1311.0502.5	Existing Structural Elements Carrying Lateral Loads (Additions)	Y	Renumbered and revised in 2024.			Send to Structural TAG.					
5-9	5	502.5			Smoke Barriers in Group I-1, Cond. 2 (Additions)		New in 2024. Addresses smoke barriers in additions to I-1 Cond. 2.	H	L		A				

5-10	5		502.6	1311.0502.6	Smoke Alarms in Existing Portions of a Building (Additions) - Relocated	Y	Relocated in 2021. Now addressed in 307.1. See also CCP-EB-1.	H	L	Amendment not needed here - address in 307.1.	AM				
5-11	5	502.6	502.6		Enhanced Classroom Acoustics (Additions)		New in 2021. Requires enhanced acoustics in additions with a volume of 20K cf or less. References ICC A117.1 accessibility standard.	H	M	Coordinate with 1341 TAG.	A				
5-12	5	503.1	503.1	1311.0503.1	General (Alterations)	Y	Reworded in 2021, structural revision in 2024. MN amendment modifies exceptions.			Coordinate with Structural TAG.	AM				
5-13	5	503.3		1311.0503.3	Existing Structural Elements Carrying Gravity Load (Alterations)	Y	No changes in 2021 or 2024.			Send to Structural TAG.	AM				
5-14	5	503.4	503.4	1311.0503.4	Existing Structural Elements Carrying Lateral Loads (Alterations)	Y	Exceptions 1 revised & 2 added in 2021. Further revision of Exception 1, and addition of Exception 3 in 2024 related to seismic. MN amendment rewords Exception 1.			Send to Structural TAG.	AM				
5-15	5	503.5			Seismic Design Category F		Seismic revised in 2024. Proposed CC-P to replace with Reroofing.			See proposed amendment CCP-EB-5 replacing this section.					
5-16	5	503.5		1311.0503.5	Reroofing (Alterations)		Proposal deletes seismic provision, replaces with direction to comply with 1305 for reroofing.			See CCP-EB-5. Also CCP-EB-7					
5-17	5	503.6, 503.7, 503.8, 503.9, 503.10, 503.11, 503.12, 503.13			Bracing and Anchorage for Parapets, Bracing and Anchorage for Masonry Walls, Substantial Structural Alteration, Roof Diaphragms Resisting Wind Loads, Voluntary Lateral-Force Resisting Systems (Alterations)		Several 2024 changes in these sections, some referencing IEBC Ch 3. Roof Diaphragm revised 2021 and 2024.			Send to Structural TAG.					
5-18	5	503.14	503.14		Smoke Compartments (Alterations)		Relocated 2021. Was under Refuge Areas. Addresses smoke compartments in I-2s for alterations. Language changed in 2021. No changes in 2024.	L	L		A				
5-19	5			1311.0503.14	Smoke Alarms in Existing Portions of a Building (Alterations) - Relocated to 307.1	Y	Smoke alarms relocated to 307.1 in 2021. See also CCP-EB-1. One exception added.	H	L	Current amendment to 503.14 not needed here 307.1 needs this amendment.	AM				

5-19	5			1311.0503.15	Carbon Monoxide Alarms	Y	CO alarms relocated to 308 in 2021. Two exceptions added.	H	L	Current amendment to 503.15 not needed here. 308 needs amendment.	AM				
5-20	5	503.15	503.15		Refuge Areas		Revised in 2021. Minor change in 2024.	H	L	From 2018: 503.16.1 Smoke Compartments now in 503.14; 503.16.2 Ambulatory Care now in 503.17; 503.16.3 Horizontal Exits address here in 503.15.	A				
5-21	5	503.16, 503.16.1			Conditions for Group I-1 Occupancies; Smoke Barriers in Group I-1, Cond. 2		New in 2024.	H	M		A				
5-22	5	503.17			Ambulatory Care Facilities		New language in 2024. Was under Refuge Areas.	H	M		A				
5-23	5	503.18	503.16		Enhanced Classroom Acoustics (Alterations)		New in 2021. Renumbered in 2024	H	M	Coordinate with 1341.	A				
5-24	5	503.19	503.17		Locking Arrangements in Educational Occupancies		New in 2021. Renumbered in 2024. Reference to IBC numbering is incorrect in model code. Should be 1010.2.7.	H	M	Watch for errata. Reference to 1010.2.8 was renumbered to 1010.2.7.	A				
5-25	5	503.20	503.18		Two-Way Communication Systems		New in 2021. Renumbered in 2024.	H	M		A				
				1311.503.21	Elevator Hoistway Opening Protection	Y				See CCP-EB-6					
5-26	5	505.1	505.1	505.1	Replacement Windows		Changed "glass" to "windows" in 2021. No change in 2024.	L	L		A				
5-27	5	505.2	505.2	505.2	Window Fall Prevention on Replacement Windows		Sub-section revised in 2021. Renamed in 2024 from "Window Opening Control Devices on Replacement Windows" to new heading.	H	L		A				
5-28	5	505.3; 505.3.1	505.3; 503.3.1	505.3	Replacement Window Emergency Escape and Rescue Openings		Some changes in 2021, including separating Control Devices to a sub-section. Only revised IRC citation in 2024.	H	L		A				
5-29	5			1311.0505.3.1	Licensed Facilities	Y	Addresses requirements for foster care, day care licensed or registered by the State.	H	L	Coordinate with Fire Code	AM				
5-30	5	505.4	505.4		Bars, Grilles, Covers or Screens		Renamed in 2021 to "Bars, Grilles, Covers or Screens". Was "Emergency Escape and Rescue Openings"	H	L		AM				

5-30.1	5			1311.0505.4	Windows and Emergency Escape Openings	Y	Amendment removes reference to Smoke Alarms in model code. Smoke Alarms are addressed elsewhere.	H	L	Revise amendment to address 505.4 Item 4.	AM				
5-31	5	506.1	506.1	1311.0506.1	Compliance	Y	MN amendment references the Life-Safety and Fire Risk Table 506.1.	H	L	Carry over.	AM				
5-32	5			1311.0506.1.2	Small Assembly Spaces	Y	Language similar to IBC Ch 3.	M	L		AM				
5-33	5	506.4	506.4		Existing Emergency Escape and Rescue Openings (Change of Occupancy)		Added to 506 Change of Occupancy in 2021.	H	M	Consider whether amendment needed for consistency with Fire Code.	AM				
5-34	5	506.5.3	506.5.3; 506.5.4	506.4.3; 506.4.4	Seismic Loads (seismic force-resisting system); Access to Risk Category IV		Changes in 2021 and 2024				A				
5-35	5	506.6	506.6		Enhanced Classroom Acoustics (Change of Occupancy)		Added to 506 Change of Occupancy in 2021.	H	M	Coordinate with 1341.	A				
Chapter 6 Classification of Work (Work Area Compliance)															
6-1	6	601.1			General Scope		Change in 2024. Removes moved buildings from scope for Classification of Work method.	L	L		A				
6-2	6	603.1	603.1		Scope		Change in 2021. Adds qualifier that Level 2 Alterations are work area less than 50% of building area where within the scope of work described. Exception clarifies exempt items.	L	L		A				
Chapter 7 Alterations - Level 1															
7-1	7	701.3			Flood Hazard Areas Level 1 Alterations		Change in numbering for work in flood hazard area. MR 1311.0010 Subp. 3, C already sends this to MR Chapter 1335	L	L		A				
7-2	7	702.4	702.4		Window Fall Prevention		2021 changes "bottom of sill" to "bottom of the clear opening". 2024 Changes title of section and adds "or other window fall prevention devices".	H	L	Confirm consistent with 1305 and 1309.	A				
7-3	7	702.5	702.5		Replacement Window for Emergency Escape and Rescue Openings		2021 added "for" in section title. Renumbered reference to IRC and IBC sections. Sends replacement windows for change of occupancy to IEBC Ch 10.	H	L		AM				

7-4	7			1311.0702	Replacement Window Emergency Escape and Rescue Openings; Licensed Facilities	Y	Amends and adds subsection 702.5.1. Removes reference to IRC buildings; combines window opening control devices (found in subsection 702.5.1 in model codes) to main section. Added subsection 702.5.1 addresses foster care or day care licensed or registered by state of MN.	H	L	Need amendment to remove IRC buildings. Could leave Control Devices as 702.5.1 and make Licensed Facilities 702.5.2. Must confirm provisions for licensed facilities include all relevant types of licenses and that req.'s match MDH and MN Fire Code. Renumber from 702.5.1 to 702.5.2 and carry forward.	AM				
7-5	7	702.5.1	702.5.1		Control Devices (Replacement EEROs)		New sub-section for control devices for replacement EEROs added in 2021.	H	L		A				
7-6	7	702.6	702.6		Bars, Grilles, Covers or Screens		New section in 2021. Allows if meeting clear opening for code under which building was constructed.	H	L	Amend to be consistent with 1311.0505.4.	AM				
7-7	7	704.1.1	704.1.1		Projections in Nursing Home Corridors (Means of Egress)		New in 2021.	H	L		A				
7-8	7	704.2	704.2		Casework (MOE)		New in 2021	H	L		A				
7-9	7	704.3	704.3		Locking Arrangements in Educational Occupancies (MOE)		New in 2021. Includes E, B ed occupancies, and I-4.	H	M	Watch for errata. Reference to 1010.2.8 was renumbered to 1010.2.7.	A				
7-10	7				General - Reroofing		CCP for Ex. 2			See CCP-EB-7					
7-11	7	705.1			General - Reroofing		For Ex. 1 and 2, adds requirement to comply with IBC Snow and Rain Loads			Send to Structural TAG.					
7-12	7		705.2		Structural and Construction Loads		Section deleted in 2021.			Send to Structural TAG.					
7-13	7	705.2			Roof Replacement		Changed in 2024. Now 3 exceptions to removal of all existing layers of coverings down to deck.	L	L		A				
7-14	7	705.3			Roof Recovering Over Wood Shingles or Shakes		Renumbered in 2024.	L	L		A				
7-15	7	705.3.1			Roof Recovering Over Wood Shingles or Shakes		Renumbered in 2024; Renamed in 2024; Added "panel products" to gypsum in 2024.	L	L		A				

7-16	7			1311.0706.2	Addition or Replacement of Roofing or Replacement of Equipment	Y				Send to Structural TAG.				
7-17	7	706.3.1			Bracing for Unreinforced Masonry Bearing Wall Parapets		Change in 2024.			Send to Structural TAG.				
7-18	7	706.3.2	706.3.2		Roof Diaphragms Resisting Wind Loads in High-Wing Regions		Change in 2021 and again in 2024.			Send to Structural TAG.				
7-19	7	707	707		Health Care Facilities		Added in 2021. I-2s, ACFs, outpatient clinics altered electrical systems comply with NFPA 99.	H	L	Electrical unit is aware of change.	A			
7-20	7			1311.0707	Energy Conservation	Y	Sends Ch 7 Energy to MN Energy Code 1322 and 1323				AM			