



What's wrong with this picture?

No fall protection while setting pre-stressed concrete at a height of more than six feet